SCHEDULE.

	S.	D.
Measures of length:—		
Each measure of a dekametre or 10 metres, including its sub-divisions—		
When the number of sub-divisions does not exceed 100 - - -	0	3
When the number of sub-divisions exceeds 100—		
For the first 100 sub-divisions	0	3
For each additional 100 sub-divisions or any number less than 100 - - - -	0	3
Each measure of a double metre or 2 metres, including its sub-divisions—		
When the number of sub-divisions does not exceed 100 - - -	0	2
When the number of sub-divisions exceeds 100—		
For the first 100 sub-divisions	0	2
For each additional 100 sub-divisions or any number less than 100 - - - -	0	2
Each measure of a metre and under, including its sub-divisions—		
When the number of sub-divisions does not exceed 100 - - -	0	1
When the number of sub-divisions exceeds 100—		
For the first 100 sub-divisions	0	1
For each additional 100 sub-divisions or any number less than 100 - - - -	0	1
Measures of capacity:—		
Each measure of 20 litres (double dekalitre)	0	3
" " " 10 " (dekalitre) - -	0	3
" " " 5 " - - - -	0	2
" " " 2 " - - - -	0	2
" " " 1 litre to 0·001 litre (millilitre) inclusive - - - -	0	1
Cubic measure:—		
Each sub-divided measure—		
When the number of sub-divisions does not exceed 10 - - -	0	1
When the number of sub-divisions exceeds 10—		
For the first 10 sub-divisions -	0	1
For each additional 10 sub-divisions or any number less than 10 - - - -	0	1
Each separate measure (not graduated) from 1000 cubic centimetres to 1 cubic centimetre (1000 cubic millimetres) inclusive - - - - - - -	0	1
Weights:—		
Each weight of 20 kilograms - -	0	3
" " " 10 " - -	0	3
" " " 5 " - -	0	2
" " " 2 " - -	0	2
" " from 1 kilogram (1000 grammes) to 1 milligram, inclusive -	0	1
Weighing instruments:—		
For 10 tonnes (10,000 kilograms) and above - - - - - - -	10	0
For under 10 tonnes (10,000 kilograms) and above 1 tonne (1000 kilograms) -	5	0
For 1 tonne (1000 kilograms) and above 250 kilograms - - - - -	2	0
For 250 kilograms and above 50 kilograms - - - - - - -	1	6
For 50 kilograms and above 25 kilograms - - - - - - -	1	0
Exclusive of cost of cartage and lifting of standards in each of above cases.		
For 25 kilograms and above 5 kilograms	0	6
" 5 " " 0·5 kilogram	0	3
" 0·5 kilogram and under - -	0	2

SCOTTISH OFFICE, WHITEHALL, S.W.,
November 4, 1901.

The King has been pleased, by Warrant under His Majesty's Royal Sign Manual, bearing date 30th ultimo, to appoint John Cairns, Esquire, Assistant Clerk in the Court of Session, to be a Depute Clerk in the Court of Session, in the room of Graham Marrable, Esquire, resigned.

FOREIGN OFFICE, October 19, 1901.

The King has been graciously pleased to appoint Reginald Thomas Tower, Esq., to be His Majesty's Envoy Extraordinary and Minister Plenipotentiary to His Majesty the King of Siam, and also to be His Majesty's Consul-General in Siam.

CROWN OFFICE, November 2, 1901.

The King has been pleased, by Letters Patent under the Great Seal, to grant unto Sir John Charles Day, Knt., late one of the Justices of His Majesty's High Court of Justice, an annuity of £3500.

CROWN OFFICE, November 2, 1901.

The King has been pleased, by Letters Patent under the Great Seal, to grant unto the Right Honourable Sir John Rigby, Knt., late a Lord Justice of Appeal, an annuity of £3500.

CROWN OFFICE, November 2, 1901.

The King has been pleased, by Letters Patent under the Great Seal, to grant unto the Honourable Sir Herbert Hardy Cozens-Hardy, Knt., the office of one of the Lords Justices of Appeal.

CROWN OFFICE, November 2, 1901.

The King has been pleased, by Letters Patent under the Great Seal, to grant unto Arthur Richard Jelf, Esq., K.C., the office of one of the Justices of the High Court of Justice.