



No. 891.—SCOTLAND—EAST COAST.

Peterhead—Alteration in Harbours.

Particulars.—The reproduction of portions of Chart No. 1438, given below, show the alterations which have been made in the depths by dredging, the reconstruction of the piers, and the positions of lights in Peterhead Harbours.

Position.—Southern entrance red light; lat. $57^{\circ} 30' N.$, long. $1^{\circ} 46\frac{1}{4}' W.$

LARGE SCALE.



Caution.—The greatest caution must be exercised in passing the submerged position of Birnie's Pier.

Chart affected.—No. 1438, Peterhead.

Publications.—List of Lights, Part 1, 1908, No. 500; North Sea Pilot, Part II, 1905, pages 164, 165; Notices to Mariners, Nos. 249 and 924 of 1907.

Authority.—Peterhead Harbour Trustees, 22nd April, 1908.

No. 892.—BALTIC ENTRANCE—
THE KATTEGAT.*Hertha Flat—Intended Buoy.*

Particulars.—During July, 1908, a buoy of the undermentioned description will be established on the shoal head recently found near the Hertha Flat in the Kattegat.

Position of shoal head.—At a distance of about $9\frac{1}{2}$ miles S. $47^{\circ} E.$ from the Skaw Light-house; lat. $57^{\circ} 38\frac{3}{4}' N.$, long. $10^{\circ} 53\frac{1}{4}' E.$, on Chart No. 2114.

Description.—A conical buoy painted in red and white vertical stripes.

Variation.— $10^{\circ} W.$

Charts affected.—No. 2114, The Kattegat; No. 2289, The Skagerrak; No. 2642a, Baltic.

Publications.—Baltic Pilot, Part 1, 1904, page 99; Notice to Mariners, No. 604 of 1908.

Authority.—Copenhagen Notice, No. 1115 of 1908.

No. 893.—FRANCE—NORTH COAST.

Trouville, East Jetty Light—Character Altered.

Particulars.—The fixed white light on the east jetty head at Trouville has been altered to a light of the following description:—

Position.—Lat. $49^{\circ} 22' N.$, long. $0^{\circ} 4\frac{1}{2}' E.$

Character.—Group occulting, showing groups of three eclipses every eighteen seconds.