

Character.—White flashing every fifteen seconds, thus:—Light, 3 seconds; eclipse, 12 seconds.

Charts affected.—No 1845, Moulmein River; No. 3481, Moulmein River to Yé River; No. 823, Koronge Island to White Point; No. 830, Bassein River to Pulo Penang; No. 70, Bay of Bengal.

Publications.—List of Lights, Part VI, 1908, No. 378; Bay of Bengal Pilot, 1901, page 374.

Authority.—R.I.M. Surveying vessel Investigator, Hydrographic Note, No. 12 of 1908.

No. 951.—JAVA—NORTH COAST.

*Inderamayu West Road—Intended Light-Buoy.*

Particulars.—A light-buoy of the undermentioned description will be established in Inderamayu West Road, as follows:—

Position.—In a depth of 5 fathoms; lat. 6° 14' 25" S., long. 108° 13' 55" E.

Description.—A light-buoy, painted in red and black horizontal stripes, exhibiting a white occulting light every twenty seconds, thus:—Light, 10 seconds; eclipse, 10 seconds.

Chart affected.—No. 1653, Java, western portion.

Publication.—Eastern Archipelago, Part II, 1904, page 98.

Authority.—Hague Notice, No. 1047 of 1908.

No. 952.—THE PHILIPPINE ISLANDS—MASBATE, NORTH COAST.

*Port Barrera—Light Established.*

Particulars.—A light of the undermentioned

character has been established in Port Barrera as follows:—

Position.—On Colorado Point, western side of entrance to harbour; lat. 12° 32' 30" N., long. 123° 22' 40" E., on Chart No. 3369.

Character.—Red fixed.

Elevation.—103 feet.

Visibility.—7 miles.

Structure.—Concrete house, 16 feet high.

Charts affected.—No. 3369, Luzon to Masbate Island; No. 2577, St. Bernardino and Mindoro Sea; No. 943, Molucca Passage to Manila.

Publications.—List of Lights, Part VI, 1908, page 133; Eastern Archipelago, Part I, 1902, page 343; Supplement, 1906; Notice to Mariners, No. 689 of 1908.

Authority.—Manila Notice, No. 31 of 1908.

No. 953.—THE PHILIPPINE ISLANDS—MASBATE, WEST COAST.

*Bugui Point—Shoal in Southern Approach.*

Particulars.—A shoal of the undermentioned description is reported to exist in the southern approach to Bugui Point, as follows:—

Position.—With Gato Island S. 40° E., distant 4 miles; Bugui Point Light N. 35° E.; lat. 12° 29' 20" N., long. 123° 9' 45" E.

Depth.—4 fathoms (estimated).

Description.—Small extent.

Variation.—1° E.

Charts affected.—No. 3369, Luzon to Masbate Island; No. 2577, St. Bernardino and Mindoro Sea; No. 943, Molucca Passage to Manila.

Publication.—Eastern Archipelago, Part I, 1902, page 253.

Authority.—Manila Notice, No. 30 of 1908.

No. 954.—THE PHILIPPINE ISLANDS—MINDANAO, SOUTH COAST.

*Sibuguey Bay—Shoals in.*

Particulars.—The undermentioned shoals exist in Sibuguey Bay as given below.

Position.—Pandalusan Island, lat. 7° 28' N., long. 122° 39' E. on Chart No. 2578.

	Position.	Depth.
At a distance of $2\frac{4}{10}$ miles	N. 59° W. from Pandalusan Island.	3 feet.
" "	20 $\frac{3}{4}$ " N. 47° E. " Tulnalutan "	4 $\frac{1}{2}$ fathoms.
" "	19 $\frac{3}{4}$ " N. 52° E. " " "	5 $\frac{1}{2}$ "
" "	17 " N. 52° E. " " "	3 $\frac{1}{4}$ "
" "	14 $\frac{1}{4}$ " N. 41° E. " " "	5 "
" "	10 $\frac{1}{4}$ " N. 45° E. " " "	2 $\frac{1}{2}$ "
" "	11 $\frac{3}{4}$ " N. 54° E. " " "	Not given.
" "	14 $\frac{1}{4}$ " N. 62° E. " " "	"

Remarks.—The above depths have not been reduced to low water. These dangers, which are steep-to, are distinguished by discoloration of the water, with the exception of the 3-foot shoal north-westward of Pandalusan Island.

Variation.—2° E.

Charts affected.—No. 943, The Philippine Islands; No. 2578, Sulu or Mindoro Sea.

Publication.—Eastern Archipelago, Part I, 1902, pages 392, 393.

Authority.—Manila Notice, No. 35 of 1908.