a distance of 3 cables north from that rock, or with Diamond Island flagstaff bearing S. 19° W., distant one mile.

Approximate position on Chart No. 834, lat. 15°  $52\frac{3}{4}$ ' N., long. 94°  $17\frac{1}{4}$ ' E.

On the same date the Fairway Buoy situated 11 cables north-eastward of the flagstaff will be withdrawn.

[Variation 1° Easterly in 1904.]

This Notice affects the following Admiralty Charts:--Preparis, North Channel, No. 152; Bassein River, No. 834. Also, Bay of Bengal Pilot, 1901, page 341.

# No. 572.—BURMA.

# Bassein River-Wreck in Eastern Approach.

The Government of India has given notice, dated 8th June, 1904, that a large spar or mast has been observed between Alguada and Baragua Lights.

Approximate position, lat. 15° 20' N., long.  $94^{\circ} 30\frac{1}{4}$ ' E.

This spar appeared to be attached to the bottom in a depth of 26 fathoms.

This Notice affects, temporarily, the following Admiralty Chart :---Preparis, North Channel, No. 152. Also, Bay of Bengal Pilot, 1901, page 344.

# No. 573.—COCHIN CHINA.

#### Pulo Cecir de Terre-Shoal off.

The French Government has given notice, dated 21st June, 1904, that the Captain of the Messageries Maritimes steamship "Ernest Simons" reports having obtained a sounding of  $4\frac{3}{4}$  fathoms to the eastward of Pulo Cecir de Terre, in a position from which the north-east point of that island bore N. 76° W., distant about 2 miles, and Logan Point S. 68° W.

Approximate position on Chart No. 1261, lat 11° 13 $\frac{1}{2}$  N., long. 108° 51 $\frac{3}{4}$  E.

[Variation 2° Easterly in 1904.]

This Notice affects the following Admiralty Chart:—Saigon River to Kamranh Bay, No. 1261. Also, China Sea Directory, Vol. II, 1899, page 395.

# No. 574.—FRANCE, WEST COAST—BAIE DE QUIBERON.

La Teignouse Light-Replaced by Temporary Light.

With reference to Notice to Mariners No. 399 of 1904 :---

The French Government has given further notice, that on 6th July, 1904, during alterations, the red flashing light on La Teignouse would be replaced by a white fixed light, of 80 candle power, exhibited from the gallery of the lighthouse; this light will be strengthened when inline with Port Navalo Lights on a N. 59° E. bearing, but it will be obscured by the lighthouse between the bearings of S. 61° E., through south, and S. 59° W. The new light may also be exhibited experimentally at the same time.

No. 27697.

Approximate position, lat. 47° 28' N., long. 3° 3' W.

Further notice will be given when the new light is established.

[Variation 16° Westerly in 1904.]

This Notice affects the following Admiralty Charts:-Bourgneuf to Ile de Groix, No. 2646; Rade de Croisic to Presqu'ile de Quiberon, No. 2353. Also, List of Lights, Part IV, 1904, No. 310; Sailing Directions for the West Coasts of France, &c, 1900, page 121; and Supplement, 1903, page 13.

# No. 575.—MEDITERRANEAN—PANTEL-LARIA ISLAND.

# Spadillo Point Light-Amended Character of.

The Italian Government has given notice, dated 2nd July, 1904, that Spadillo Point Light, Pantellaria Island, is a flashing and not an occulting light, and has a period of thirty (not twenty) seconds, thus:—flash, eleven seconds; eclipse, nineteen seconds.

Approximate position, lat. 36°  $49\frac{1}{2}$ ' N., long. 12° 1' E.

This Notice affects the following Admiralty Charts:--Mediterranean Sea, Nos. 449, 2158*a*, 2158*b*; Sardinia to Malta, No. 165; Mazzara to Palma, No. 186. Also, List of Lights, Part V, 1904, No. 543; Mediterranean Pilot, Vol. I, 1894, page 327; and Supplement, 1898, page 14.

# No. 576.—NEWFOUNDLAND.

# Bank off South Coast.

Information, dated 20th June, 1904, has been received from Commodore Alfred Paget, His Majesty's ship "Charybdis," of the existence of a bank, about 9 miles off Lamalin Harbour on the south coast of Newfoundland. From a survey made under the Commodore's direction, this bank, which appears to be composed of stones, is, as defined by the 40-fathoms contour line, about 5 miles long in an easterly and westerly direction, and  $3\frac{1}{2}$  miles broad, with depths of from 29 fathoms over it on its southern 3

Approximate position of 29 fathoms, latitude 46° 41' N., longitude 55° 46' W.

A new edition of Chart No. 893 will be issued.

This Notice affects the following Admiralty Charts:---St. John's to Halifax, No. 2666; Gulf of St. Lawrence, No. 2516; Newfoundland, No. 232*a*; Burin Harbour to Devil Bay, No. 893. Also, Newfoundland, &c., Pilot, 1897, page 117.

No. 577.—CANADA—RIVER ST. LAWRENCE. Quebec Approaches—Light-Buoys Established and Altered.

The Government of the Dominion of Canada ..... has given notice, dated 6th June, 1904, that the