bears east, distant 2 miles, and Sagasau Island | Bay, that the fixed light on the jetty head at

Approximate position, lat. 11° $10\frac{3}{4}$ ° N., long. 124° $24\frac{3}{4}$ ° E.

This reef, which is about half a mile long in a north-north-westerly and south-south-easterly direction, and a quarter of a mile broad, consists of coral with scattered boulders, with depths of 3 or 4 fathoms between them.

In the passage between this reef and the reef extending eastward from Jau Island there are depths of from 5 to 6 fathoms.

[Variation 1° Easterly in 1908.]

This Notice affects the following Admiralty Chart:—Sulu or Mindoro Sea, No. 2578. Also, Eastern Archipelago, Part I, 1902, page 291; and Supplement, 1906.

No. 123.—THE PHILIPPINE ISLANDS— SAMAR, SOUTH COAST.

San Pedro Bay—Shoal Reported in.

The United States Government has given notice, dated 3rd January, 1908, that a shoal, with a least depth of 23 fathoms over it, is reported to exist in San Pedro and San Pablo Bay in a position from which Punubulu Island bears N. 9° W., distant $2\frac{8}{10}$ miles, and Dio Island

Approximate position, lat. 11° 10′ 35″ N., long. 125° 6′ 35″ E.

This shoal, which is about 60 yards long by 2) yards broad, consists of coral and rock; there are depths of 10 fathoms around it.

[Variation 1° Easterly in 1908.]

This Notice_affects_the following Admiralty Charts:—San Pedro Bay to Libukan Islands, No. 2987; Sulu or Mindoro Sea, No. 2578; the Philippine Islands, No. 2577. Al Archipelago, Part I, 1902, page 363. Also, Eastern

No. 124.—BORNEO—NORTH COAST.

Baguan Island-Rock Reported North-West of.

The Harbour Master, Hong Kong, has given notice, dated 10th December, 1907, that the Master of the Norwegian steamship Progress reports that his vessel struck on a pinnacle rock, with a depth of 3 fathoms over it, off the north coast of Borneo, at a distance of 2 miles N. 50° W. from Baguan Island.

Approximate position, lat. 6° $7\frac{3}{4}$ ′ N., long. 118° $25\frac{1}{2}$ ′ E.

[Variation 2° Easterly in 1908.]

This Notice affects the following Admiralty Charts:—Gaya Bay to Sandakan Harbour, No. 287; Sulu Archipelago, No. 2576; China Sea, No. 2660b. Also, Eastern Archipelago, Part I, 1902, page 166.

No. 125.—SOUTH AFRICA—CAPE COLONY.

Mossel Bay-Alteration in Lights.

· Information, dated 20th December, 1907, has

Aliwal shows red between the bearings of S. 22° W. and S. 37° W., and green when bearing to the westward of S. 37° W.

Approximate position, lat. 34° 11′ S., long. 22° 9′ E.

Also, that the red fixed light formerly exhibited in Erme Bay, about one mile to the westward, has been discontinued.

[Variation 29° Westerly in 1908.]

This Notice affects the following Admiralty Chart:—Mossel Bay, No. 639. Also, List of Lights, Part VI, 1907, No. 12, and Remarks; and Africa Pilot, Vol. III, 1905, pages 105, 107.

No. 126.—UNITED STATES—ATLANTIC COAST, LONG ISLAND SOUND.

New Haven - Wreck in Approach, Light-Buoy.

The United States Government has given notice, dated 3rd January, 1908, that the wrecks of two coal boats lie sunk in the approach to New Haven. A light-buoy, painted red, exhibiting a red occulting light every twenty seconds (light, ten seconds; eclipse, ten seconds), has been moored in a depth of $4\frac{1}{2}$ fathoms at a distance of 50 yards south-eastward of the wrecks, in a position from which Merwins Point bears N. 58° W., distant 12 cables, and Clark Point N. 6° W. The depth over the wrecks is

Approximate position, lat. 41° 13' N., long. 72° 58′ W.

Variation 10° Westerly in 1908.]

This Notice affects the following Admiralty Chart:—Long Island Sound, No. 2755. Also, Sailing Directions for the East Coast of the United States, 1899, page 459,

No. 127.—UNITED STATES—GULF OF MEXICO, FLORIDA, PENSACOLA BAY.

Devil's Point Light—Re-Established and Altered

With reference to Notice to Mariners No. 1220 of 1906:-

The United States Government has given further notice, that on 23rd December, 1907, a white fixed lantern light, elevated 30 feet above high water, was established in a white pile structure erected on the site of the red fixed light which was washed away from Devil's Point in Escambia Bay.

Approximate position, lat. 30° $29\frac{1}{2}$ ′ N., long. 87° $8\frac{1}{2}$ ′ W.

This Notice affects the following Admiralty Chart:—San Blas to Vermilion Bay, No. 1467. Also, List of Lights, Part VIII, 1907, No. 1592; and West India Pilot, Vol. I, 1903, page 561.

No. 128.—WEST INDIES, PUERTO RICO-WEST COAST.

Corsica (Corcega) Sugar Mill-Light Exhibited from; Caution.

The United States Government has given been received from the Harbour Master, Mossel I notice, dated 3rd January, 1908, that a white